

State of Utah **DEPARTMENT OF NATURAL RESOURCES** Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program Date: June 22, 2009

Reviewed:

Mine Name: Maynard Topaz	Permit Number: S/023/0099		
Operator Name: Colorado Calumet Co. Inc	Inspection Date: June 17, 2009		
Inspector(s): Wayne Western & Brett Gregory	Time: 3:30 – 3:50 pm		
Other Participants: None	Mine Status ACT		

		Elements of Inspection	Evaluated	Comment	Enforcement
1		Permits, Revisions, Transfer, Bonds		\boxtimes	
2		Public Safety (shafts, adits, trash, signs, highwalls)		\boxtimes	
3		Protection of Drainages / Erosion Control			
4		Deleterious Material		\boxtimes	
5		Roads (maintenance, surfacing, dust control, safety)			
6		Concurrent Reclamation			
7		Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8		Water Impoundments			
9		Soils			
1	0.	Re-vegetation			
1	1.	Air Quality			
1	2.	Other			

Bond Amount:

Bond \$15,400.

Permit fee:

July 22, 2008 - \$150.

Purpose of Inspection:

Routine Inspection

Inspection Summary:

The Permittee installed fences above the pit. The main pit is approximately 25 feet deep. No topsoil was stockpiled.

On site is a trailer and camper shell that have been vandalized. The Division considers those items to be deleterious materials because the Permittee cannot utilize them.

Inspection Date: June 17, 2009

Page 2 of 3 M/023/0099

Directions:

See GIS file for map. Drive north on main road until one passes the site. Then turn south on two-wheel track and proceed south.

Conclusions and Recommendations:

The Permittee should remove or rehabilitate the trailer and camper shell. The Permittee should stockpile topsoil before any new surface disturbance.

Lapo Water

Inspector's Signature

WHW BG

cc: (OPERATOR) (SITLA)

O:\M023-Juab\S0230099-MaynardTopaz\inspections\ins-06-17-2009.doc

Inspection Date: June 17, 2009 Page 3 of 3 M/023/0099

